



PRODUCT CHANGE

NEW SIDE SUPPORT PLATE FOR FOOTBOX HD BALANCE

Footbox std & short

ART.NO. 62981/63981/64981/65981/62982/63982/64982/65982

As requested by customers and in order to secure supply, HD Rehab is making a change to the Side Support plate for HD Balance. The material of the Side support plate will be changing to ABS. This does not change the function or quality of the product, but it does simplify reconditioning.

The change will start being implemented in the 2nd quarter, 2024

Footbox will keep the same article numbers, but the numbers for the side support plate will change.

Outgoing articles

art.no. 63986 Footbox Side Pad standard right art.no. 63987 Footbox Side Pad standard left

art.no. 64986 Footbox Side Pad short right art.no. 64987 Footbox Side Pad short left

New articles

art.no. 62986-2 Side Support Plate ABS std right art.no. 62986-1 Side Support Plate ABS std left

art.no. 62987-2 Side Support Plate ABS short right art.no. 62987-1 Side Support Plate ABS short left





HD Rehab AB Tryffelslingan 4, SE-181 57 Lidingö