

NEW FOOTREST SIDE FOR HD BALANCE

Footrest Side

ART.NO. 65986/65987

As requested by customers and in order to secure supply, HD Rehab is making a change to the Footrest side plate for HD Balance. The material of the Footrest side plate will be changing to ABS. This does not change the function or quality of the product, but it does simplify reconditioning.

The change will start being implemented in the 2nd quarter, 2024

Footrest Side will keep the same article numbers, but the numbers for the side support plate will change.

Outgoing articles

art.no. 65986-1 Footrest Side right

art.no. 65987-1 Footrest Side left

New articles

art.no. 62988-2 Side Support Plate ABS right

art.no. 62988-1 Side Support Plate ABS left



New version



Outgoing version